
FIG. 1



2/7

FIG. 2





FIG. 3



ij	
10 20	
ļa nš s	
17.02	
18	~
ing.	•
.,	~ I
"LI	C
	Ц
u přis	

	50			4		4/7								
	3/2/2001		Respor	Enviror	Environ	Plant /			Hazar	Plant /		Mainte	Enviro	
		xport	Priority	High	Very High	High	Medium		High			Medium	Low	
		Print / Export	Date Due	06/01/2000	10/01/2000 Very High Enviror	12/01/1999	11/17/2000	11/16/2000	01/01/2000	03/01/2000	11/15/2000	01/01/2000	03/01/2000	
		Chooser	Status											
1. 6. 402	FILTERS (HELP)	f 61		Submit Tier II forms to the local fire department and document the submittal.	Characterize laboratory waste and cleaning solvent to determine if they are hazardous wastes.	Contact TSDF to determine status of waste shipments.	8		Close all containers of hazardous waste in the satellite accumulation area.	Arrange facility inspection by local fire department.		Have SPCC Plan reviewed and certified by a Professional Engineer.	Identify the facility's emergency response	
ļ		4	豊	102- 7	103-1	103-2	103-3	103-4	103-5	103-6	103-7	103-8	103-9	•
405	ORGANIZATION (FILTERS)	中心 \ Organization 中央 \ Acme Company>	中文 ({18) Chemical Division>	古文(445) Examples> 中文	中心 (3) 1999	(13) June	☐ (3) November (10) October	白女 Y Resp. Person H 女 {9}	TS {7} Environmental Coordinator S {9} Facilities Manager	─────────────────────────────────────	[6] Maintenance Supervisor	(3) Training manager		11 414 418 444 400

FIG. 5




FIG. 6

	<u>6</u>			4			6/7						Þ	
	3/2/2001		Respo	Enviro	Environ	Envirol Coordi	Safety	Safety	Enviror	Envirol Coordi	Safety	Safety	Enviro	
		xport	Priority	High	Very High	Low	High	High		Medium	High	High		
		Print / Export	Date Due	06/01/2000	10/01/2000 Very High Enviro	03/01/2000	01/01/2000	01/01/2000	03/01/2000	03/01/2000	01/01/2000	01/01/2000	03/01/2000	
		hooser	Status											
402	FILTERS HELP	1 of 13 Detail Split Window Show Field Chooser			103- 1 Characterize laboratory waste and cleaning solvent to determine if they are hazardous wastes.	103-9 Identify the facility's emergency response contractor in the SPCC Plan.	03- 13 Provide eye protection for workers in the parts cleaning area.	9		406- 9 Identify the facility's emergency response contractor in the SPCC Plan.	406- 13 Provide eye protection for workers in the parts cleaning area.	406- 16 Install an emergency shower/eyewash station in the forklift battery recharging area.	509-1 Characterize laboratory waste and cleaning solvent	
(4		<u> </u>	5	2	9	9	9	8	40	400	200	\
405	ORGANIZATION FILTERS	라이지 Organization 라이지 Acme Company>	한지 7(5) Chemical Division>	→ 上	中文画 null 1999		- (1) Julie - (5) March	Let 1/3 October Health 7/2 Resp. Person	Environmental Coordinator		☐ Joe Smith ☐ Maintenance Supervisor	├── Frant Manager ├─☑ {6} Safety Engineer ├── (Training manager		

FIG. 7

